



**COMMUNITY**  
connectivity program

# Torrington

East Main Street Corridor – Road Safety Audit

April 2016



**AECOM**

Built to deliver a better world

Acknowledgements:

OFFICE OF INTERMODAL PLANNING  
BUREAU OF POLICY AND PLANNING  
CONNECTICUT DEPARTMENT OF TRANSPORTATION

With assistance from AECOM Transportation Planning Group

# Contents

1	Introduction to East Main Street - Torrington RSA.....	5
1.1	Location .....	5
2	Pre-audit Assessment of Location .....	8
2.1	Pre-audit Information .....	8
2.2	Prior Successful Efforts.....	13
2.3	Pre-Audit Meeting .....	13
3	RSA Assessment.....	14
3.1	Field Audit Observations .....	14
3.2	Post Audit Workshop - Key Issues .....	17
4	Recommendations .....	17
4.1	Short Term .....	17
4.2	Medium Term .....	20
4.3	Long Term.....	22
4.4	Summary.....	24

# Figures

Figure 1.	East Main Street Corridor.....	6
Figure 2.	5-way Intersection.....	7
Figure 3.	Crashes that Occurred in 2015 (Connecticut Crash Data Repository) .....	10
Figure 4.	East Main Street Road Geometrics.....	11
Figure 5.	Split Pedestrian Phase .....	14
Figure 6.	Broken Sidewalk Ramp.....	15
Figure 7.	Pedestrian Push Button Far from Crosswalk.....	15
Figure 8.	Pedestrian Crossing Mid-block by the Library .....	15
Figure 9.	Island that acts as a Sidewalk.....	16
Figure 10.	Non-Compliant ADA Ramp, Faded Crosswalk .....	16
Figure 11.	Pedestrian Crossing Sign not Near a Sidewalk.....	16
Figure 12.	Vegetation Encroaching on the Sidewalk .....	17
Figure 13.	Short Term Recommendations .....	19
Figure 14.	Pedestrian Countdown Signal .....	20
Figure 15.	Pedestrian Crossing Sign.....	20
Figure 16.	"No Turn on Red" Sign.....	20
Figure 17.	Medium Term Recommendations .....	21

Figure 18. Typical Pedestrian Crossing Bump outs ..... 22  
Figure 19. Long Term Recommendations ..... 23

## **Tables**


Table 1. Crash Severity 2012-2014..... 9  
Table 2. Crash Type 2012-2014 ..... 9  
Table 3. Intersection Street Inventory ..... 12



The Connecticut Department of Transportation (CTDOT) is undertaking a Community Connectivity Program that focuses on improving the state's transportation network for all users, with an emphasis on bicyclists and pedestrians. A major component of this program is conducting Road Safety Audits (RSA's) at selected locations. An RSA is a formal safety assessment of the existing conditions of walking and biking routes and is intended to identify the issues that may discourage or prevent walking and bicycling. It is a qualitative review by an independent team experienced in traffic, pedestrian, and bicycle operations and design that considers the safety of all road users and proactively assesses mitigation measures to improve the safe operation of the facility by reducing the potential crash risk frequency or severity.

The RSA team is made up of CTDOT staff, municipal officials and staff, enforcement agents, AECOM staff, and community leaders. An RSA Team is established for each municipality based on the requirements of the individual location. They assess and review factors that can promote or obstruct safe walking and bicycling routes. These factors include traffic volumes and speeds, topography, presence or absence of bicycle lanes or sidewalks, and social influences.

Each RSA was conducted using RSA protocols published by the FHWA. For details on this program, please refer to [www.ctconnectivity.com](http://www.ctconnectivity.com). Prior to the site visit, area topography and land use characteristics are examined using available mapping and imagery. Potential sight distance issues, sidewalk locations, on-street and off-street parking, and bicycle facilities are also investigated using available resources. The site visit includes a "Pre-Audit" meeting, the "Field Audit" itself, and a "Post-Audit" meeting to discuss the field observations and formulate recommendations. This procedure is discussed in the following sections.



## 1 Introduction to East Main Street - Torrington RSA

The City of Torrington submitted an application to complete an RSA along the East Main Street Corridor, from the 5-way downtown intersection at Main Street easterly to the town line, to improve safety for pedestrians and bicyclists. The high traffic volume, numerous driveways and steep terrain contribute to a confusing and potentially unsafe environment for these pedestrians and bicyclists. Specifically, the town has noted significant pedestrian activity despite the high traffic volumes and limited sidewalks. This is evident by the many paths worn into grass areas along the corridor, signifying the need for a better pedestrian environment.

The City of Torrington's application contained information on traffic volumes, crash data, and mapping. The application and supporting documentation are included in Appendix A.

### 1.1 Location

The RSA site consists of the 3.5 mile long East Main Street (Route 202) corridor between the 5-way downtown intersection with Main Street and the New Hartford town line (Figure 1). It includes the downtown intersection of East Main Street, Main Street, South Main Street, Water Street and Franklin Street, as well as the Litchfield Street/South Main Street intersection. The corridor carries a significant amount of local traffic because of substantial commercial development and the fact that it is the primary access to the downtown area. It also carries significant through traffic movements, as Route 202 is the primary east/west corridor in this area of the state, bisected by State Routes 4, 8 (Exit 44) and 183.

The Average Daily Traffic (ADT) in the corridor varies between 15,400 veh./day and 21,100 veh./day, except for the portion where Route 4 overlaps Route 202, and the ADT is 25,000 veh./day. These are significant volumes of traffic for the corridor to process.



**Figure 1. East Main Street Corridor**

East Main Street is a state owned and maintained facility (Route 202), and runs in a relatively straight south east/north west direction. Route 202 is the primary commercial corridor and has some of the highest traffic counts in Torrington. The numerous businesses, which range in size from a few employees to over 100, provide employment and services to the residents of Torrington and surrounding towns. There is high pedestrian activity despite large sections of the corridor with limited, no or poor condition sidewalks. Between the downtown area and Route 8, East Main Street consists of a single lane in each direction with parking on both sides of the street. East of Route 8, a second uphill (eastbound) lane is added to assist with the uphill traffic capacity. Between Greenridge Road and the town line, the roadway consists of two through lanes in each direction. Turn lanes are provided at most intersections.

The 5-way downtown intersection is the convergence of Water Street, Main Street, East Main Street, South Main Street and Franklin Street (Figure 2). South Main Street is on a bridge structure over the Naugatuck River, and intersects with Litchfield Street on the south side of the bridge. Route 202 is a "dog-leg" that uses East Main Street to the east, and Litchfield Street to the west, connected by the South Main Street Bridge. The intersection is confusing and challenging for drivers to traverse, with each leg containing multiple lanes. Similarly,

pedestrians must follow a difficult path using multiple pedestrian phases to cross this expansive area.

Because of the complexity of this intersection, it is not pedestrian or bike friendly, and it creates a significant pedestrian disconnect between the downtown core and areas south of the Naugatuck River. In April 2016, the City, in conjunction with CTDOT, began the second phase 2 of a Streetscape project along Main Street from Water Street to Maiden Lane. The re-design includes new sidewalk infrastructure, pedestrian friendly amenities, landscaping and lighting.



Figure 2. 5-way Intersection



There are sidewalks on both sides of the roadway between downtown and the Route 8 interchange. Sidewalk continues up the hill on the north side only, to a point just beyond Fern Drive. Through the rest of the corridor, sidewalk is located sporadically, typically being found in front of more recent commercial developments, where sidewalk access was required by the City. The sidewalks are generally 5 feet in width, but have little or no snow shelf or buffer from the roadway traffic. The sidewalks are generally concrete but there are old sections of asphalt sidewalk, some of which is in poor condition. Table 3 provides a summary of the street inventory and sidewalk conditions.

There are several other projects in development which will have a significant impact on the corridor. These include:

- A new Supreme Court House is currently being constructed ½ mile north of the 5-way intersection. It is scheduled to open late 2016 or early 2017. The new court house will relocate jobs to this area, create additional economic activity downtown, and increase traffic in this area.
- A new trail head for the Naugatuck River greenway is proposed within 500' of the 5-Way intersection.
- As part of the City's Master Development Plan, Franklin Street will be closed to motorized traffic to convert the street into a pedestrian friendly area and connect to the Greenway trail head.
- Continuation of the Naugatuck River Greenway toward Stillwater pond will require crossing of the 5-way intersection.
- As part of the planned Sue Grossman Greenway Expansion, the trail would be expanded from its trailhead at Buttrick Road to connect with the Naugatuck River Greenway.

## 2 Pre-audit Assessment of Location

### 2.1 Pre-audit Information

As noted above, traffic volumes are significant at this location. The crash history shows that the largest number of crashes involves rear end accidents. The crashes tend to be clustered around high volume intersections (Figure 3). This is indicative of congestion coupled with access management issues (many driveways). The peak crash rate occurs in the afternoon, which is generally attributed to commuting, shopping, and school activities that peak during this time.

Severity Type	Number of Accidents	
Property Damage Only	337	76%
Injury (No fatality)	108	24%
<b>Total</b>	<b>445</b>	

**Table 1. Crash Severity 2012-2014**

Source: UConn Connecticut Crash Data Repository

Manner of Crash / Collision Impact	Number of Accidents	
<b>Unknown</b>	5	1%
<b>Sideswipe-Same Direction</b>	43	10%
<b>Rear-end</b>	214	48%
<b>Turning-Intersecting Paths</b>	73	16%
<b>Turning-Opposite Direction</b>	31	7%
<b>Fixed Object</b>	17	4%
<b>Backing</b>	11	2%
<b>Angle</b>	13	3%
<b>Turning-Same Direction</b>	20	4%
<b>Moving Object</b>	1	0%
<b>Parking</b>	4	1%
<b>Pedestrian</b>	6	1%
<b>Overturn</b>	1	0%
<b>Head-on</b>	2	0%
<b>Sideswipe-Opposite Direction</b>	4	1%
<b>Total</b>	<b>445</b>	

**Table 2. Crash Type 2012-2014**

Source: UConn Connecticut Crash Data Repository




Figure 3. Crashes that Occurred in 2015 (Connecticut Crash Data Repository)

Torrington E. Main St




Figure 4. East Main Street Road Geometrics

## Torrington - East Main Street Street Inventory

From	To	Distance	Width	Sidewalk				Curb	Parking	Shoulder	Ramps	
				Side	Type	Width	Condition				Exist	Compliant
5-way	Rt 8 S on-ramp	0.5 miles	1 lane	EB	Concrete	6' - 12'	Fair	Concrete	Yes	7'	50%	No
			1 lane	WB	Concrete	6' - 12'	Fair	Concrete	Yes	7'	50%	No
Rt 8 S on-ramp	Bird Street	0.3 miles	2 lanes	EB	Concrete	5'	Fair	Concrete	No	2'	No	No
			1 lane	WB	Concrete	5'	Fair	Concrete	No	2'	No	No
Bird Street	Fern Drive	900 feet	2 lanes	EB	No	N/A	N/A	Concrete	No	1'	N/A	N/A
			1 lane	WB	Concrete	4'	Fair	Concrete	No	2'	Yes	No
Fern Drive	Buena Vista Ave	0.8 miles	2 lanes	EB	No	N/A	N/A	Concrete	No	2'-6"	No	No
			1 lane	WB	No	N/A	N/A	Concrete	No	2'	No	No
Buena Vista Ave	Torringford West St	800 feet	2 lanes	EB	Asphalt	4'	Poor	Concrete	No	1'	Yes	No
			1 lane	WB	No	N/A	N/A	Concrete	No	2'	No	No
Torringford West St	Torringford St	0.7 miles	2 lanes	EB	No	N/A	N/A	Asphalt	No	6"	No	No
			1 lane	WB	No	N/A	N/A	Asphalt	No	2'	No	No
Torringford St	Target Entrance	1200 feet	2 lanes	EB	Concrete	5'	Good	Asphalt	No	2'	Yes	Yes
			3 lanes	WB	No	N/A	N/A	Asphalt	No	2'	Yes	yes
Target Entrance	Torringford E. St	0.3 miles	2 lanes	EB	No	N/A	N/A	Asphalt	No	4'	No	No
			1 lane	WB	No	N/A	N/A	Asphalt	No	4'	No	No

\*CONDITION – "Good" is Serviceable Condition that meets current design standards. "Fair" is generally serviceable, but may need minor repairs, or may not completely align with current design standards. "Poor" is not serviceable, and generally inadequate for continued long-term use.

Table 3. Intersection Street Inventory

## 2.2 Prior Successful Efforts

The City of Torrington has executed a construction program that will improve streetscape elements throughout the downtown area, and make Main Street more attractive as well as functional for all users. They have worked toward the completion of several hiking/bicycle trails and coordinated these efforts with adjacent towns. They have funding in place to plan additional trail connections as well as to continue construction of these facilities, with a goal of a complete trail system throughout the community. Present plans include accommodating trailheads near the 5-way intersection.

Zoning regulations provide for the construction of new sidewalks as developments are approved. This, however, is a lengthy process, and does not provide a mechanism for correcting gaps in the pedestrian paths. With an overall plan in place, it will be possible to direct funding in a way that is most effective for providing a safe pedestrian environment.

## 2.3 Pre-Audit Meeting

The RSA was conducted on April 6, 2016. The Pre-Audit meeting was held at 9:00 AM in the Torrington City Hall, located at 140 Main Street, Torrington.

The RSA Team was comprised of staff from AECOM, staff from CTDOT and representatives from several Torrington departments and organizations including the Engineering Department, Police Department, Mayor's office, Planning and Economic Development Department, Fire Department and Inland-Wetlands Office. The complete list of attendees can be found in Appendix B.

Several items were presented and discussed during the pre-audit meeting:

- Crash data:
  - This is a busy corridor with a typical number of crashes; 1% involved pedestrians.
  - A higher concentration of crashes occurs during the evening commute.
  - The predominant type of crash (rear-end) is typical for a congested roadway with frequent driveways.
- Previous CTDOT thinking was focused on vehicular traffic only, with little focus on other transportation modes. Now CTDOT is looking at ways to balance the ability to accommodate vehicular traffic and still provide pedestrians with a safe and attractive environment.
- 5-way intersection
  - It is important to make this area safer and more inviting for pedestrians.
  - The City is currently working with CTDOT to redesign the intersection but it is still in preliminary phases.
  - The City recently received a brownfield grant to redesign Franklin St. Closing it to create a pedestrian walkway is being considered.

- The city would like to explore ways to connect the existing greenway to the proposed trail located across the intersection.
- This intersection moves a lot of vehicles.
- In summer 2015 the city held charrettes to discuss pedestrian access through the 5-way intersection. They would like to connect the downtown to Coe Park.
- There is a new court house being constructed to the north, and it is anticipated that many people will access it from Route 8 via Pearl St. Improving this corridor would help alleviate traffic at the 5-way intersection.
- Some of the pedestrian crossings are long, with a pedestrian island and split phase. This can be confusing. The islands feel unsafe.
- The islands in and around the 5-way intersection act as guides for vehicular traffic.
- Some of the pedestrian crossings do not seem to provide enough time to cross.
- CTDOT is looking at retiming the signals, installing bump outs and reducing the crossing width and number of lanes.
- East Main Street
  - This corridor experiences a lot of pedestrian activity as evident by the paths worn in the grass.
  - Any new commercial centers are required to install sidewalks. This is good, but has left the corridor fragmented.
  - Some sidewalks are in poor condition, have crossing buttons to nowhere, are not ADA compliant and falling apart.
  - The RT 8 interchange at Burger King will need to be redeveloped in the future.
  - The intersection of East Main Street and Tarringford West Street has senior housing on both sides but lacks pedestrian access.
  - The city does desire bike facilities along Route 202 and has recently formed a bike advocate group to accommodate bicyclists. They are looking at bike lanes, sharrows, cycle tracks, wider shoulders and diverting bikes to local roads.

### 3 RSA Assessment

#### 3.1 Field Audit Observations

##### 5-way Intersection

- Across East Main there is a split pedestrian phase. The pedestrian island appears to originally have stamped concrete and then was paved over (Figure 5). The paving is falling apart here causing a tripping hazard.



Figure 5. Split Pedestrian Phase

- Pedestrian signal heads do not have a countdown.
- Curb cuts are missing tactile warning strips.
- There is a lack of pedestrian crossing signage.
- This is a concurrent pedestrian signal.
- The 99 Plaza has two entrances. The city is looking into eliminating the one closest to the 5-way intersection. This would allow for the stop bar to be moved up and provide a more direct crossing to Coe Park.
- The pedestrian waiting area on the bridge is narrow and feels unsafe.
- The city is looking into extending the island on the bridge towards the park but there are concerns about weight and structural loads on the bridge.
- Some of the sidewalk ramps are broken and have missing chunks of concrete (Figure 6).
- The push button between Franklin and East Main Street is located farther than maximum allowed from the actual crossing (Figure 7).
- It should be investigated as to whether a multi-use path could be installed on the bridge to connect the greenway from Franklin Street across the river. The current sidewalk width is about 8' with a 2' shoulder.
- A pedestrian was observed crossing mid-block between Coe Park and the library even though the crosswalk was within 100 feet. It was noted that the crosswalk is twice as long and requires two signal phases to complete the crossing (Figure 8).
- There is a general lack of pedestrian way-finding.
- The downtown lacks a gateway.
- This intersection can be confusing to motorists.
- The stop bar on Mason Street is set back very far.
- Some of the cross walks are faded.



Figure 6. Broken Sidewalk Ramp



Figure 7. Pedestrian Push Button Far from Crosswalk



Figure 8. Pedestrian Crossing Mid-block by the Library



## Torryford West Street & East Main Street

- Some paved islands are acting as narrow sidewalks. (Figure 9).
- The intersection angles are skewed, creating a 45 degree angle. To improve the radius of the corners with sharper turns the curb has been pulled back. This creates longer crossing distances for pedestrians.
- The shoulders are very narrow. Many intersections have been retrofitted to include a turning lane.
- Route 202's position on the Vendor-In-Place (VIP) list should be checked.
- Utility poles and signs are in the way of sidewalks.
- The cross slopes of sidewalks in some locations do not meet ADA guidelines (Figure 10).
- There are ramps for pedestrian signals but no sidewalks.
- This intersection has an audible pedestrian phase.
- The crosswalk paint is worn out.
- Driveways are numerous and large. In some places it becomes difficult to discern the roadway from a private property such as at Jimmy's Store at the southwest corner of the intersection.
- There are no pedestrian crossing signs (although there is one mid-block before the next intersection. (Figure 11).



Figure 9. Island that acts as a Sidewalk



Figure 10. Non-Compliant ADA Ramp, Faded Crosswalk

## Routes 4 and 8 access to Route 202

- The sidewalk has guide rail on both sides of the road on the steep grade.
- This is an exclusive pedestrian signal.
- One pedestrian push button is missing the directions plate.



Figure 11. Pedestrian Crossing Sign not Near a Sidewalk

- Right turn on red from Elm Street to Route 202 is permitted, although this is a difficult turn because of the skew of the intersection and the grades.
- Plantings encroach on the sidewalk (Figure 12).



Figure 12. Vegetation Encroaching on the Sidewalk

### 3.2 Post Audit Workshop - Key Issues

The following issues were discussed:

- Future funding for further studies or engineering design has not been determined at this point.
- The State is going to incorporate these RSA plans and their information into the Statewide Bicycle and Pedestrian Plan.
- The plan will include general and specific recommendations.
- It is anticipated that the audit report will be completed in 4 to 6 weeks.
- With a Master Plan in place, it is relatively easy to get commercial developments to provide portions of the plan as a condition of approval.
- There is a branding and imaging plan for the city outlining wayfinding. Once funding is available they will begin to implement it.

## 4 Recommendations

From the discussions during the Post-Audit meeting, the RSA team compiled a set of recommendations that are divided into short-term, mid-term, and long-term categories. For the purposes of the RSA, **Short-term** is understood to mean modifications that can be expected to be completed very quickly, perhaps within six months, and certainly in less than a year if funding is available. These include relatively low-cost alternatives, such as striping and signing, and items that do not require additional study, design, or investigation (such as right-of way acquisition). **Mid-term** recommendations may be more costly and require establishment of a funding source, or they may need some additional study or design in order to be accomplished. Nonetheless, they are relatively quick turn-around items, and should not require significant lengths of time before they can be implemented. Generally, they should be completed within a window of eighteen months to two years if funding is available. **Long-term** improvements are those that require substantial study and engineering, and may require significant funding mechanisms and/or right-of-way acquisition. These projects generally fall into a horizon of two years or more when funding is available.

### 4.1 Short Term

1. When Route 202 is scheduled for repaving, restripe to allow for wider shoulder on the uphill side for cyclists.

2. Repaint crossings.
3. Incorporate the Branding and Imaging Plan as well as the corridor plan into any redevelopment.
4. Redesign East Main Street in phases; it is too much to accomplish at once.
5. Require all new developments to add sidewalks.
6. Patch sidewalks where they are uneven or broken.
7. Remove or cut back encroaching vegetation.




Figure 13. Short Term Recommendations

## 4.2 Medium Term

1. A Master Plan needs to be developed for East Main Street with a corridor study that looks at access management, ROW, traffic, intersections, and pedestrian amenities. This plan could establish policies for future development and be used as a basis for updating current zoning regulations.
2. Close Franklin Street and make it a pedestrian only area.
3. Connect the existing and proposed greenway over the bridge by widening the sidewalk to create a multi-use trail on one side.
4. Redesign East Main Street in phases; it is too much to accomplish at once.
5. Add sidewalks in the areas where there are direct connections such as at Tarringford West & East Main Street.
6. Replace pedestrian signals with countdown signals (Figure 14).
7. Add audible devices to all pedestrian signals.
8. Add tactile warning strips to all crossings.
9. Make all crossings ADA compliant.
10. Relocate all signs out of the pedestrian way.
11. Complete sidewalk mapping.
12. Add pedestrian crossing signs (Figure 15) and relocate existing improperly located signs.
13. Fix broken pedestrian push buttons.
14. Implement wayfinding for pedestrians and vehicular traffic.
15. Add no turn on red sign (Figure 16) from Elm Street to Route 202.
16. Evaluate pedestrian signal timings and adjust accordingly to meet new standards.
17. Relocate pedestrian pushbuttons that do not meet current standards.



Figure 14. Pedestrian Countdown Signal



Figure 15. Pedestrian Crossing Sign



Figure 16. "No Turn on Red" Sign




Figure 17. Medium Term Recommendations

### 4.3 Long Term

1. Incorporate the Branding and Imaging Plan as well as the corridor plan into any redevelopment.
2. Close Franklin St and make it a pedestrian only area.
3. Connect the existing and proposed greenway over the bridge by widening the sidewalk to create a multi-use trail on one side.
4. Redesign East Main Street in phases; it is too much to accomplish at once.
5. Fill in the missing sidewalk gaps along East Main Street.
6. Fix areas with cross slope issues.
7. Eliminate the entrance by the 5-way intersection for the 99 plaza and move up the stop bar to create a more direct crossing to Coe Park.
8. Implement Access Management Plan to consolidate driveways.
9. Narrow crossings at 5-way to eliminate split phases and waiting islands.
10. Add bump outs (Figure 18) at crossings to shorten crossing distance.
11. Create a gateway to downtown.
12. Reconstruct the Pearl Street and East Pearl Street intersection in order to reduce traffic at the 5-way intersection. This would make the 5-way intersection more pedestrian and bicycle friendly.



**Figure 18. Typical Pedestrian Crossing Bump outs**




Figure 19. Long Term Recommendations



#### 4.4 Summary

This report outlines the observations, discussions and recommendations developed during the RSA. It documents the successful completion of the City of Torrington RSA and provides Torrington with an outlined strategy to improve the transportation network along the East Main Street corridor and 5-way intersection for all road users, particularly focusing on pedestrians and cyclists. Moving forward, Torrington may use this report to prepare strategies for funding and implementing the improvements, and as a tool to plan for including these recommendations into future development along East Main Street and the 5-way intersection.



**COMMUNITY**  
connectivity program

# Appendix A



**AECOM**  
Built to deliver a better world

# Welcome to the Community Connectivity Program Application



Please fill in the following information to provide the Audit team leaders with a comprehensive description of the area contained in this application.

## 1. Applicant contact information

<b>Name</b>	<input type="text"/>
<b>Title</b>	<input type="text"/>
<b>Email Address</b>	<input type="text"/>
<b>Telephone Number</b>	<input type="text"/>

## 2. Location information

<b>Address</b>	<input type="text"/>
<b>Description</b>	<input type="text"/>
<b>City / Town</b>	<input type="text"/>

**3. Roadway type**  
**(Please select all that apply)**

State road

Local road

Private Road

Other (please specify)

**4. Zoning**  
**(Please select all that apply)**

Industrial

Residential

Commercial

Mixed Use

Retail

N/A (not applicable)

Other (please specify)

**5. Approximate mile radius around the location**

Other (Please Specify)

**6. Community Sites**  
**(Please select all that apply)**

Community Centers

Business Districts

Restaurant/Bar Districts

Churches

Housing Complexes

Proximity to Schools

Tourist Locations (examples – Casino, Malls, Parks, Aquarium, etc...)

N/A (not applicable)

Other (please specify)

**7. Employment Facilities**  
**(Retail, Industrial, etc...)**

Yes

No

**If Yes please describe (please specify)**

**8. Educational facilities**

**(Please select all that apply)**

Public, Parochial, Private Schools (more than 1 school within a ½ mile)

University / Community Colleges

N/A (not applicable)

Other (please specify)

**9. Transit facilities**

**(Please select all that apply)**

Bus

Rail

Ferry

Airport

Park and Ride Lot

N/A (not applicable)

Other (please specify)

**10. Safety Concerns**

**(Please select all that apply)**

Traffic (volumes & speed)

Collisions

Sidewalks

Traffic Signals

Traffic Signs

Parking Restrictions / Additions

Drainage

ADA Accommodations

Agricultural & Live Stock crossing


Maintenance issues (cutting grass, leaves, snow removal)

N/A (not applicable)

Other (please specify)

**11. Are there any past, current or future transportation/economic development projects near this location (i.e. Federal, State or local projects)?**


**If Yes please describe and list all projects.**

A large, empty rectangular box with a thin black border, intended for the user to describe and list any past, current, or future transportation or economic development projects near the location. The box is currently blank.




**12. Environmental Concerns:**

**If Yes please describe and list.**


A large, empty rectangular box with a thin black border, intended for the user to describe and list any environmental concerns. The box occupies most of the page's vertical space below the instruction.

**13. Please explain why this location should be considered for an RSA**

A large, empty rectangular box with a thin black border, intended for the user to provide an explanation for why a location should be considered for an RSA. The box occupies most of the page's vertical space below the question.

**14. Are there plans to expand the area?**

(Transportation Oriented Development, Economic Development, housing, etc...)



**15. Any other pertinent information that is unique to this location?**

A large, empty rectangular box with a thin black border, intended for the user to provide any other pertinent information unique to the location.

**Thank you for completing the Community Connectivity application.**

**Please click on the "submit button" below and include the following attachments**

- 1 Location map (google, GIS) **(Required)**
- 2 Collision data (If available)
- 3 Traffic data (ADT or VMT) (If available)
- 4 Pedestrian/bicycle data (If available)



**COMMUNITY**  
connectivity program

# Appendix B



**AECOM**  
Built to deliver a better world



## Road Safety Audit

**Town:** Torrington  
**RSA Location:** East Main Street Corridor  
**Meeting Location:** City Hall  
**Address:** 140 Main Street  
**Date:** 4/6/2016  
**Time:** 9:00 AM

## Participating Audit Team Members

Column1	Column2
Audit Team Member	Agency/Affiliation
Krystal Oldread	AECOM
Kevin Tedesco	CTDOT
Stephen Gazillo	AECOM
Paul Metsack	CTDOT
Shivani Mahajan	AECOM
Steve Mitchell	AECOM
Matt Walsh	City of Torrington
Rista Malanca	City of Torrington
Marty Connor	City of Torrington
Officer Steve Pisarski	City of Torrington - Police
Tim Waldron	City of Torrington - Mayors Office
Chief Gary Brunoli	City of Torrington - Fire Dept
Erin Wilson	City of Torrington - economic Development
Ed Fabbri	City of Torrington - city engineer
Mayor Elinor Carbone	City of Torrington - Mayors Office



**COMMUNITY**  
connectivity program

# Appendix C



**AECOM**  
Built to deliver a better world





## Road Safety Audit – Torrington

**Meeting Location:** Torrington City Hall  
**Address:** 140 Main Street  
**Date:** 4/6/2016  
**Time:** 9:00 AM

### Agenda

- Type of Meeting:** Road Safety Audit – Pedestrian Safety
- Attendees:** Invited Participants to Comprise a Multidisciplinary Team
- Please Bring:** Thoughts and Enthusiasm!!
- 9:00 AM**                      **Welcome and Introductions**
- Purpose and Goals
  - Agenda
- 9:15 AM**                      **Pre-Audit**
- Schedule
  - Safety Procedures
  - Review Site Specific Data:
    - Average Daily Traffic
    - Crash Data
    - Geometrics
  - Issues
- 10:15 AM**                      **Audit**
- Visit Site
  - As a group, identify areas for improvements
- 11:30 PM**                      **Post-Audit Discussion / Completion of RSA**
- Discussion observations and finalize findings
  - Discuss potential improvements and final recommendations
  - Next Steps
- 1:00 PM**                      **Adjourn for the Day – but the RSA has not ended**

#### Instruction for Participants:

- Before attending the RSA, participants are encouraged to observe the intersection and complete/consider elements on the RSA Prompt List with a focus on safety.
- All participants will be actively involved in the process throughout. Participants are encouraged to come with thoughts and ideas, but are reminded that the synergy that develops and respect for others' opinions are key elements to the success of the overall RSA process.
- After the RSA meeting, participants will be asked to comment and respond to the document materials to assure it is reflective of the RSA completed by the multidisciplinary team.



# Road Safety Audit – Torrington – East Main Street

**Meeting Location:** Torrington City Hall  
**Address:** 140 Main Street  
**Date:** 4/6/2016  
**Time:** 9:00 AM

## Audit Checklist

Pedestrians and Bicycles	Comment
<p><b>Pedestrian Crossings</b></p> <ul style="list-style-type: none"><li>• Sufficient time to cross (signal)</li><li>• Signage</li><li>• Pavement Markings</li><li>• Detectable warning devices (signal)</li><li>• Adequate sight distance</li><li>• Wheelchair accessible ramps<ul style="list-style-type: none"><li>○ Grades</li><li>○ Orientation</li><li>○ Tactile Warning Strips</li></ul></li><li>• Pedestrian refuge at islands</li><li>• Other</li></ul>	
<p><b>Pedestrian Facilities</b></p> <ul style="list-style-type: none"><li>• Sidewalk<ul style="list-style-type: none"><li>○ Width</li><li>○ Grade</li><li>○ Materials/Condition</li><li>○ Drainage</li><li>○ Buffer</li></ul></li><li>• Pedestrian lighting</li><li>• Pedestrian amenities (benches, trash receptacles)</li><li>• Other</li></ul>	




<p><b>Bicycles</b></p> <ul style="list-style-type: none"> <li>• Bicycle facilities/design</li> <li>• Separation from traffic</li> <li>• Conflicts with on-street parking</li> <li>• Pedestrian Conflicts</li> <li>• Bicycle signal detection</li> <li>• Visibility</li> <li>• Roadway speed limit</li> <li>• Bicycle signage/markings</li> <li>• Shared Lane Width</li> <li>• Shoulder condition/width</li> <li>• Traffic volume</li> <li>• Heavy vehicles</li> <li>• Pavement condition</li> <li>• Other</li> </ul>	
--	--

<p><b>Roadway &amp; Vehicles</b></p>	
<ul style="list-style-type: none"> <li>• Speed-related issues             <ul style="list-style-type: none"> <li>○ Alignment;</li> <li>○ Driver compliance with speed limits</li> <li>○ Sight distance adequacy</li> <li>○ Safe passing opportunities</li> </ul> </li> </ul>	
<ul style="list-style-type: none"> <li>• Geometry             <ul style="list-style-type: none"> <li>○ Road width (lanes, shoulders, medians);</li> <li>○ Access points;</li> <li>○ Drainage</li> <li>○ Tapers and lane shifts</li> <li>○ Roadside clear zone /slopes</li> <li>○ Guide rails / protection systems</li> </ul> </li> </ul>	
<ul style="list-style-type: none"> <li>• Intersections             <ul style="list-style-type: none"> <li>○ Geometrics</li> <li>○ Sight Distance</li> <li>○ Traffic control devices</li> <li>○ Safe storage for turning vehicles</li> <li>○ Capacity Issues</li> </ul> </li> </ul>	
<ul style="list-style-type: none"> <li>• Pavement             <ul style="list-style-type: none"> <li>○ Pavement Condition (excessive roughness or rutting, potholes, loose material)</li> <li>○ Edge drop-offs</li> </ul> </li> </ul>	



<ul style="list-style-type: none"><li>○ Drainage issues</li><li>● Lighting Adequacy</li></ul>	
<ul style="list-style-type: none"><li>● Signing<ul style="list-style-type: none"><li>○ Correct use of signing</li><li>○ Clear Message</li><li>○ Good placement for visibility</li><li>○ Adequate retroreflectivity</li></ul></li><li>● Proper support</li></ul>	
<ul style="list-style-type: none"><li>● Signals<ul style="list-style-type: none"><li>○ Proper visibility</li><li>○ Proper operation</li><li>○ Efficient operation</li><li>○ Safe placement of equipment</li><li>○ Proper sight distance</li><li>○ Adequate capacity</li></ul></li></ul>	
<ul style="list-style-type: none"><li>● Pavement Markings<ul style="list-style-type: none"><li>○ Correct and consistent with MUTCD</li><li>○ Adequate visibility</li><li>○ Condition</li><li>○ Edgelines provided</li></ul></li></ul>	
<ul style="list-style-type: none"><li>● Miscellaneous<ul style="list-style-type: none"><li>○ Weather conditions impact on design features.</li><li>○ Snow storage</li></ul></li></ul>	






**Total Accidents Shown With Map Symbols**

Extrication of victim(s) from vehicle =	5
Motor vehicle accident with injuries =	77
Motor vehicle accident with no injuries =	146
<b>TOTAL</b>	<b>228</b>

115 Additional accidents occurred in the Corridor but are not shown with map symbols. These did not have an address number associated with the incident, and can not be geocoded.

- Points of Interest**
- EMS
  - Animal Control
  - Cemetery
  - City Hall
  - Community Center
  - Family Court
  - Fire Station
  - Golf Course
  - Health District
  - Hospital
  - Housing Authority
  - Library
  - Park
  - Parking
  - Parks Department
  - Police Station
  - School
  - State Park
  - Street Department
  - Waste Disposal
  - Water Company
  - Apartments
  - Condos



# Community Connectivity Project Road Safety Audit Corridor Vehicle Accident Locations 2008-2012

City of Torrington, Connecticut

**LEGEND**


- Traffic Count Locations
- Project Area

**Accident Locations**

- Extrication of victim(s) from vehicle
- Motor vehicle accident with injuries
- Motor vehicle accident with no injuries

Disclaimer:  
This map is not a survey and is intended as a visual reference only. The City of Torrington makes no claims as to the accuracy of data shown.

5000' State Plane Grid shown with black lines  
Geographic Coordinates shown with red lines  
- Aerial photo 2012 State of Connecticut  
- Towns and Street Data from CT DEEP GIS  
- Traffic Counts from CT DOT 2012 ADT Map  
- Accident data from Torrington Fire Marshall  
- All other data City of Torrington GIS



Drawn By: Engineering Dept. Date: 3/1/2016

File: D:\GIS\Projects\Road\_Safety\_Audit\_Corridor\Map\_Symbols\Map\_Symbols\_2016\_03\_01.mxd

Coordinate System: NAD 1983 StatePlane Connecticut FIPS 5000 Feet  
Projection: Lambert Conformal Conic  
Datum: North American 1983  
False Easting: 1000000.0000  
False Northing: 800000.0000  
Central Meridian: -72.7500  
Standard Parallel 1: 41.2000  
Standard Parallel 2: 41.8667  
Latitude Of Origin: 40.8333  
Units: Feet US



## Road Safety Audit – Torrington – East Main Street

Meeting Location: Torrington City Hall  
 Address: 140 Main Street  
 Date: 4/6/2016  
 Time: 9:00 AM

### Crash Summary

Data: 3 years (2012-2014)

**6 accidents involved pedestrians, all resulted in injuries**

**4 accidents involved bicyclists, 3 resulted in injuries**

Severity Type	Number of Accidents	
Property Damage Only	337	76%
Injury (No fatality)	108	24%
<b>Total</b>	<b>445</b>	

Manner of Crash / Collision Impact	Number of Accidents	
Unknown	5	1%
Sideswipe-Same Direction	43	10%
Rear-end	214	48%
Turning-Intersecting Paths	73	16%
Turning-Opposite Direction	31	7%
Fixed Object	17	4%
Backing	11	2%
Angle	13	3%
Turning-Same Direction	20	4%
Moving Object	1	0.2%
Parking	4	1%
Pedestrian	6	1%
Overturn	1	0.2%
Head-on	2	0.4%
Sideswipe-Opposite Direction	4	1%
<b>Total</b>	<b>445</b>	



Weather Condition	Number of Accidents	
Snow	16	4%
Rain	44	10%
No Adverse Condition	378	85%
Unknown	3	1%
Blowing Sand, Soil, Dirt or Snow	1	0.2%
Other	1	0.2%
Severe Crosswinds	1	0.2%
Sleet, Hail	1	0.2%
Total	445	

Light Condition	Number of Accidents	
Dark-Not Lighted	3	1%
Dark-Lighted	90	20%
Daylight	334	75%
Dusk	14	3%
Unknown	3	1%
Dawn	1	0.2%
Total	445	

Road Surface Condition	Number of Accidents	
Snow/Slush	12	3%
Wet	60	13%
Dry	366	82%
Unknown	3	1%
Ice	3	1%
Other	1	0.2%
Total	445	






Time		Number of Accidents	
0:00	0:59	4	0.9%
1:00	1:59	1	0.2%
2:00	2:59	1	0.2%
3:00	3:59	2	0.4%
4:00	4:59	0	0.0%
5:00	5:59	3	0.7%
6:00	6:59	4	0.9%
7:00	7:59	14	3.1%
8:00	8:59	13	2.9%
9:00	9:59	22	4.9%
10:00	10:59	14	3.1%
11:00	11:59	30	6.7%
12:00	12:59	36	8.1%
13:00	13:59	36	8.1%
14:00	14:59	42	9.4%
15:00	15:59	36	8.1%
16:00	16:59	47	10.6%
17:00	17:59	53	11.9%
18:00	18:59	28	6.3%
19:00	19:59	17	3.8%
20:00	20:59	16	3.6%
21:00	21:59	11	2.5%
22:00	22:59	11	2.5%
23:00	23:59	4	0.9%
<b>Total</b>		<b>445</b>	

# Torrington E. Main St

Legend	
	Sidewalk both sides
	Sidewalk one side
	No sidewalk
	Signalized intersection
	Crosswalk
	Bridge or culvert
	Major waterway



**DRAFT**



---

## **Road Safety Audit – Torrington – East Main Street Corridor**

**Meeting Location:** Torrington City Hall

**Address:** 140 Main Street

**Date:** 4/6/2016

**Time:** 9:00 AM

### **Post-Audit Discussion Guide**

#### **Safety Issues**

- Confirmation of safety issues identified during walking audit

#### **Potential Countermeasures**

- Short Term recommendations
  
  
  
  
  
  
  
  
  
  
- Medium Term recommendations
  
  
  
  
  
  
  
  
  
  
- Long Term recommendations

#### **Next Steps**

- Discussion regarding responsibilities for implementing the countermeasures (including funding)



## Road Safety Audit – Torrington

**Meeting Location:** Torrington City Hall  
**Address:** 140 Main Street  
**Date:** 4/6/2016  
**Time:** 9:00 AM

### Fact Sheet

#### Functional Classification:

- East Main Street (Route 202) is classified as a Principal Arterial

#### ADT

- ADT along this corridor spans between 8,600 and 25,000

#### Population and Employment Data:

- Population: 36,383
- Employment: 15,268


#### Urbanized Area

- East Main Street Corridor is located within an Urbanized Area (Torrington Urban Cluster)




#### Demographics

- The statewide average percentage below the poverty line is 10.31%. Along this corridor 10.32% - 20% of residents are below the state's poverty level



- The statewide average percentage minority population is 30.53%. Towards the western end of this corridor there is a higher concentration of minority residents.



### Air Quality

- Torrington's CIPP number 321
- Torrington is within the Greater CT Marginal Ozone Area
- Torrington is within a CO Attainment Area



**COMMUNITY**  
connectivity program

# Appendix D



**AECOM**  
Built to deliver a better world



YELLOW

SUNOCO